


FIG. 1


Organic insulating layer pattern
from glass substrate surface
– occurrence of a peeling



Organic insulating layer pattern on ITO surface
– no occurrence of a peeling

FIG. 2

Organic insulating layer pattern on ITO surface
– no occurrence of a peeling



Organic insulating layer pattern
from glass substrate surface
– occurrence of a peeling

FIG. 3A




FIG. 3B




FIG. 3C




FIG. 3D




FIG. 3E




FIG. 4A




FIG. 4B

